



**THIS NOTICE IS FOR THE INFORMATION OF
SHIP'S MASTERS AND OTHERS CONCERNED**

**FREMANTLE PORTS NOTICE TO MARINERS
16/2011**

**FREMANTLE PORT
KWINANA & COCKBURN SOUND – SPECIAL BUOYS**

Former Notice – FPA NTM 22/2006 is withdrawn.

Two special buoys with topmarks have been removed. Previous charted coordinates were as follows:

<i>Position (WGS84)</i>	<i>Previous Marker Buoy & Light Characteristics</i>
32-09.51 S 115-41.84 E	Special, Fl. Y. 4s
32-10.20 S 115-43.71 E	Special, Fl. Y. 4s



Mariners are advised to navigate with caution.

Charts Affected

RAN: Aus 111 - Aus 114 - Aus 117

DPI: WA 001

Capt A J Gray
Harbour Master
Fremantle Ports
22 August, 2011