



**THIS NOTICE IS FOR THE INFORMATION OF
SHIP'S MASTERS AND OTHERS CONCERNED**

**FREMANTLE PORTS NOTICE TO MARINERS
1(T)/2011**

**FREMANTLE PORT
INNER HARBOUR – NORTH & VICTORIA QUAYS -
Berth Depths**

Former Notice – FPA NTM 11(T)/2010 is cancelled

Due to the movement of silt alongside Fremantle Port Inner Harbour berths, results of recent capital dredging and general engineering works, the declared depths (reduced to LWM Fremantle) of each berth have been revised. Movement has typically occurred within, but is not limited to, a distance of less than 20m from the face of the berth.

North Quay		Victoria Quay	
Berth	Declared Depth	Berth	Declared Depth
1	11.0	A	*
2	11.0	B	*
4	(out of service)	C	10.4
5	(out of service)	D	11.0
6	14.0***	E	10.5
7	14.0**	F	10.4
8	14.0**	G	10.5
9	14.0**	H	10.3
10	14.0**		
11	10.2		
12	10.8		

* Berths A & B (Victoria Quay) are no longer used for commercial shipping.

** Changed data from previous FPA NTM

*** East from bollard 36.

Maximum draft of vessels using inner harbour berths **must be obtained** by contacting the Harbour Master's office.

Mariners are advised to navigate with caution.

Charts Temporarily Affected

RAN: Aus 112 - Aus 113 ; DPI: WA 001

Capt A J Gray
Harbour Master
Fremantle Ports
10 January, 2011